

## Acme Materials Cross Reference Guide

ACME	P4	P41	P42	P43	P46	P5	P51	P52	S3
TDK	PC40	PC44	PC90		PC95	PC50	PC50		
NICERA	NC-2H	2HM5	BM27			2M	5M		
EPCOS	N67,N87		N92			N49	N49		
FERROXCUBE	3C85,3C90	3C96	3C92	3C93		3F3	3F35		3R1
DMEGC	DMR40	DMR44	DMR2KB			DMR50			
TDG	TP4	TP4A	TP4S			TP5	TP5A		
TOKIN	BH2	BH1					B40		
FDK	6H20					7H10			
MAGNETICS	P					R	K		
THOMSON	F1								
TOMITA	2F8,2G8								
JFE(KAWTATETSU)	MB3	MB4			MBT1		MC2		
SAMWHA	PL-5,PL-7	PL-11				PL-F1			HS-1
ISU	PM7	PM11	BM15		PM12	FM4	FM5		
HITACHI	ML24D						ML12D		
FAIR-RITE	78								85
FERRITE INT*	TSF-7099	TSF-7060				TSF-5099			
KASCHKE	K2008								
ISKRA	45G		55G			35G		75G	

ACME	A041	A043	A05	A07	A10	A101	A102	A121	A151
TDK	DN45	DNW45	H5B	H5B2	H5C2			H5C4	H5C3
NICERA			NC-5Y	NC-7	NC-10H	10TB		12H	15H
EPCOS	T57		N30	T35/T37	T38	T38		T42	T46
FERROXCUBE			3E27	3E25/3E27	3E5	3E55		3E6	3E7
DMEGC	DMR4KDC		DMR5K	DMR7K	DMR10K			DMR12K	DMR15K
TDG			TS5	TS7	TS10/TS10A	TH10		TS13	TS15
TOKIN			5H	7H	10H			12H	15H
FDK			2H06	2H07	2H10				2H15
MAGNETICS			J		W				H
THOMSON			T6,T6A	T4A,T4					
NEOSID			F-830	F-860	F-938				F-942
TOMITA			2F1	2E1	2E2			2H2	2H1
JFE(KAWTATETSU)			MA055	MA070			MA100	MA120	MA150
SAMWHA			SM50	SM70S	SM100				SM150

STEWARD	36	46	35	37	40				
KRVSTINEL			K82	K86	K87				
HITACHI			MQ53D	MP70D	MP10T				MP15T
FAIR-RITE			75		76				
FERRITE INT <sup>™</sup>			TSF-3000		TSF-010K				
FERRONICS		BE	B		T				V
KASCHKE			K5000		K10000			K12000	K15000
ISKRA			19G	22G	12G			32G	52G

ACME	<b>N10</b>	<b>N2</b>	<b>N4</b>	<b>N42</b>	<b>N43</b>
TDK		DN45			
NICERA	WT-10		2B		
EPCOS		T57	N48	N45	M33
FERROXCUBE		3E28	3B7	3B46,3S5	3D3
DMEGC		DMR4KDC			
TDG			TH2		
SAMWHA		SM43T	SM23T		SM8T
ISU				BM30	
STEWARD		36			
HITACHI			MQ25D		